



Service Advisory

MTD-119

Tillers

Models Affected: HUSKEE/TSC - 21AA45M5031, & 21AA454E231
 MASTERCUT - 21AB452A059
 MTD GOLD - 21AB452A004

Serial Number Range Affected: Units built November 09, 2009 (Date Code "...K099...") through May 16, 2010 (Date Code "...E160...").

Date: June 11, 2010

Subject: Model 450 Series Rear Tine Tiller Shift Lever Service Kit 753-06491

PURPOSE: Service Kit 753-06491 provides the shift lever hardware and installation instructions for the model 450 Series Rear Tine Tiller to address the jumping out/disengagement of "Tines Reverse" mode on some early production units. The installation of Service Kit 753-06491 provides a positive secondary index for the transmission when in the "Tines Reverse" mode.

SYMPTOM: If the tiller exhibits jumping out/disengagement of the "Tines Reverse" mode, order and install Service Kit 753-06491. See attached Service Kit instruction sheet.

ACTION REQUIRED: This is to be considered a **Fix-As-Fail** repair on Model Year 2010 Rear Tine Tiller models listed above produced within the serial number range dates listed above.

Service Kit Contents

(See Figure 1)

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	*	1	BRACKET: SHIFT
2	*	1	BRACKET: INDEX: TRANSMISSION
3	*	1	LEVER: SHIFT
4	750-05467	1	SPACER:.33" x .50" x 1.00"
5	736-0430	1	WASHER: FLAT: .350" x 1.590" x .062"
6	736-0242	1	WASHER: BELL: .340" x .872" x .060"
7	732-0987	1	SPRING: COMP.: .72" O.D. x 2.25" LG
8	720-0313	1	GRIP: .1875" x 1.00"
9	712-04063	1	NUT: FLANGELOCK: 5/16"-18 :GRF:NYLON
10	710-3195	1	SCREW: 5/16"-18 x 4.50":GR5:STD
11	710-0599	2	SCREW: TAPTITE: 1/4"-20 x .500":HXINDWSH
12	*	1	THIS INSTRUCTION SHEET

* - Not Available Separately



FIGURE 1

Warranty: Normal warranty terms apply. Indicate Service Advisory MTD- 119 and P/N 932-0496 as the original failed part on the claim. Repair time allowance is **0.2 Hrs.**

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial