

## Service Bulletin

Date: April 17, 2003 Product Line: Snowmobile

Bulletin No: 2004-1-01 Subject: Ski Shock Upgrade

**Affected Models / VIN:** 

2003 Mountain Cat 600 EFI Models Within the VIN Ranges Indicated Below

Model: Mountain Cat EFI (136 in.) Black/Green

Model No: S2003MCD6EUSB

VIN Range: 4UF03SNW23T156018 - 4UF03SNWX3T156199

Model: Mountain Cat 600 EFI (136 in.) Black/Green - OS

Model No: S2003MCD6EOSB

VIN Range: 4UF03SNW23T156200 - 4UF03SNWX3T156266

Model: Mountain Cat 600 EFI (136 in.) Black/Red

Model No: S2003MCDE6USB

VIN Range: 4UF03SNW13T156267 - 4UF03SNW33T156366

Model: Mountain Cat 600 EFI (144 in.) Black/Red

Model No: S2003MCDE4USB

VIN Range: 4UF03SNW53T156367 - 4UF03SNW43T156666

Model: Mountain Cat 600 EFI (144 in.) Black/Green

Model No: S2003MCD4EUSB

VIN Range: 4UF03SNW63T156667 - 4UF03SNW33T157100

■ NOTE: For identification purposes, it is necessary to refer to only the last six digits of the vehicle identification number.

NOTE: In our continuing effort to produce quality products, Arctic Cat is dedicated to upgrading a product that does not meet our specification standards and/or expectations. Arctic Cat is issuing Service Bulletin 2004-1-01 to ensure that our products meet our specification standards and expectations.

**Condition:** It has been determined that the ski shocks on the affected models do not meet Arctic Cat

standards and must be replaced.

**Solution:** Replace the existing ski shocks with new Ski Shocks (p/n 2603-259). Refer to an appropriate

Arctic Cat Snowmobile Service Manual for installation instructions.

**Parts:** Order an appropriate number of new Ski Shocks (p/n 2603-259) through normal parts-ordering

channels. Your dealership Parts Account will be charged and then credited upon receipt of a

Warranty Claim Request form.

**Warranty:** A labor allowance of 0.5 hr will be paid per affected snowmobile.

Cat Tracker Claim: Enter BS200401 in the Complaint section.

Manual Claim: Enter 0401 in the Complaint section.







