



Service Bulletin

Date: November 18, 2004

Product Line: Snowmobile

Bulletin No: 2005-1-03

Subject: Improperly Tightened Torque Bracket Cover

Affected Models/VIN Range:

2005 T660 Models within the VIN Range of 4UF05SNW75T125540 - 4UF05SNW05T128425

Condition: It has come to our attention that the three screws securing the torque bracket cover may not have been tightened properly and may come loose.

Solution: Remove the screws, apply blue Loctite #243 to the screws, reinstall the screws, and tighten to the proper torque factor. Be sure to refer to the specific instructions enclosed with this bulletin.

Parts: Not Applicable (no parts are needed).

Warranty: A total labor allowance of 0.2 hr will be paid per affected snowmobile.
Cat Tracker Claim: Enter BS200503 in the Complaint section.
Manual Claim: Enter 0503 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.

ATTENTION

Completing the necessary service work as soon as possible will eliminate the possibility of related damage to the snowmobile. To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to November 18, 2005. All warranty claims directly related to this issue will not be honored after November 18, 2005.

