



Service Bulletin

Date: September 13, 2005

Product Line: OHUV

Bulletin No: 2006-6-02

Subject: Rear Gear Case Bearing Housing Assembly


Affected Models/VIN:

2006 Prowler XT Models within the Vehicle Identification Range (VIN) of 4UF06MPV06T300001-4UF06MPV86T300781 and have a serial number on the rear gear case tag within the numbers of 037-250

■ **NOTE:** For Identification purposes, it is necessary to refer to only the last six digits of the VIN.


■ **NOTE:** The tag on the rear gear case is located on the lower front left side of the gear case. See Fig. 1 and Fig. 2 for the location of tag and serial number.

Fig. 1



PR353A

Fig. 2



PR352A

Please note at this time that the vehicle may also be affected by Product Safety Recall Bulletin 2006-6-01. If this is the case, it is advisable to complete the service work for both bulletins at the same time.

Condition: It has been determined that the rear gear case bearing housing does not meet Arctic Cat specifications and must be replaced.

Solution: Replace the existing rear gear case bearing housing assembly with Rear Gear Case Housing Kit (p/n 0437-048).

■ **NOTE:** The existing rear gear case bearing housing including the U-joint must be returned to Arctic Cat.

Parts: Order an appropriate number of Rear Gear Case Housing Kit (p/n 0437-048) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.5 hr will be paid per affected vehicle.
Claim: Enter BU200602 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to September 13, 2006. All warranty claims directly related to this issue will not be honored after September 13, 2006.