



# Service Bulletin

**Date:** October 15, 2001

**Product Line:** ATV

**Bulletin No:** 2002-2-07

**Subject:** Wheel Mounting Nut - Improper Torque

**Affected Models/VIN:**

2002 300 4x4 (Red)

Model No: A2002ATF4AUSR

VIN Range: See below the following VIN numbers of affected ATV's. For identification purposes, it is necessary to check only the last six numbers in the vehicle identification number.

4UF02ATV52T225841	4UF02ATV22T225862	4UF02ATV52T226018
4UF02ATV92T225843	4UF02ATV42T225863	4UF02ATV72T226019
4UF02ATV52T225855	4UF02ATV32T225871	4UF02ATV32T226020
4UF02ATV92T225857	4UF02ATV72T226005	4UF02ATV02T226024
4UF02ATV02T225858	4UF02ATV02T226007	4UF02ATV42T226026
4UF02ATV22T225859	4UF02ATV42T226009	4UF02ATV62T226027
4UF02ATV02T225861	4UF02ATV62T226013	4UF02ATVX2T226029

**Condition:** It has been determined that the wheel mounting nuts on the affected ATV's (included in the list above) may not have been tightened to the proper torque during production.

**Solution:** Inspect the vehicle identification number of all 2002 300 4x4 (Red) ATV's at your dealership to determine if the ATV contains a VIN listed above. If the ATV contains a VIN listed above, all the wheel mounting nuts on each wheel must be tightened to 5.5 kg-m (40 ft-lb).

■ **NOTE:** To ensure that all the wheel nuts are properly tightened, loosen all the wheel nuts; then tighten each nut to the proper torque.

**Parts:** Not Applicable

**Warranty:** A labor allowance of 0.2 hr will be paid per affected ATV.

Only one vehicle identification number (VIN) per claim can be entered. Do not submit a group claim.

Enter 207A in the Complaint section of the Warranty Claim Form.

Enter p/n 0423-322 in the Failed Part No. section of the Warranty Claim Form.

■ **NOTE:** This bulletin expires on October 15, 2003.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1001



# Bulletin de Service

**Date:** Le 15 octobre 2001

**Ligne de production:** VTT

**Numéro de bulletin:** 2002-2-07

**Objet:** Écrou de montage de roue – Torsion incorrect

**Modèles concernés/NIV:**

300 4x4 (Rouge) 2002

Numéro de modèle: A2002ATF4AUSR

Gamme de NIV: Voir ci-dessous les NIV suivants, des VTT concernés. Pour fins d'identification, il est nécessaire de vérifier seulement les six derniers numéros du numéro d'identification de véhicule.

4UF02ATV52T225841	4UF02ATV22T225862	4UF02ATV52T226018
4UF02ATV92T225843	4UF02ATV42T225863	4UF02ATV72T226019
4UF02ATV52T225855	4UF02ATV32T225871	4UF02ATV32T226020
4UF02ATV92T225857	4UF02ATV72T226005	4UF02ATV02T226024
4UF02ATV02T225858	4UF02ATV02T226007	4UF02ATV42T226026
4UF02ATV22T225859	4UF02ATV42T226009	4UF02ATV62T226027
4UF02ATV02T225861	4UF02ATV62T226013	4UF02ATVX2T226029

**Condition:** Il a été déterminé que les écrous de montage de roue des VTT concernés (inclus dans la liste ci-dessus) n'ont pas été resserrés de torsion correcte durant la production.

**Solution:** Inspectez le numéro d'identification de véhicule de tous les VTT 300 4x4 (Rouge) 2002 à votre concession afin de déterminer si le VTT détient un NIV indiqué ci-dessus. Si le VTT détient un NIV indiqué ci-dessus, tous les écrous de montage de roue de chaque roue doivent être resserrés à 5,5 kg-m (40 pi-lb).

■ **REMARQUE:** Pour vous assurer que tous les écrous soient resserrés correctement, déserrez tous les écrous des roues; ensuite, resserrez chaque roue de torsion correcte.

**Pièces:** Ne s'applique pas

**Garantie:** Une allocation de main-d'oeuvre de 0,2 h sera payée par VTT concerné.

Un seul numéro d'identification de véhicule (NIV) peut être inscrit. Ne soumettez pas de réclamation en groupe.

Inscrivez 207A à la section Plainte sur le formulaire de réclamation de garantie.

Inscrivez le n/p 0423-322 à la section Numéro de pièce en panne sur le formulaire de réclamation de garantie.

■ **REMARQUE:** Ce bulletin prendra fin le 15 octobre 2003.



Imprimé aux États-Unis



®™ Marques déposées d'Arctic Cat Inc., Thief River Falls, MN 56701



1001