



# Service Bulletin

**Date:** November 25, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-18

**Subject:** In-Line Heater Location

## Affected Models / VIN:

All 2003 4-Stroke Touring (International)

Model No: S2003ACFEROSG (International)

VIN Range: 4UF03SNW43T312091 - 4UF03SNW73T312263

■ **NOTE:** Although this bulletin pertains to only the 4-Stroke Touring (International), it is also being sent to all dealerships for your information and records. This bulletin does not affect any 4-Stroke snowmobiles sold in the United States or Canada.

**Condition:** It has been determined that the in-line heater on the affected models is located too close to the alternator belt cover. This condition will cause the alternator belt cover to come into contact with the crankshaft pulley causing possible damage to the alternator belt cover.

### ⚠ CAUTION

Do not operate or permit anyone to operate an affected snowmobile until the location of the existing in-line heater has been changed.

**Solution:** Install In-Line Heater Update Kit (p/n 0637-240) according to the instructions in the kit.

■ **NOTE:** Installation of the new hoses will change the location of the in-line heater allowing adequate space between the in-line heater and the alternator belt cover.

**Parts:** An appropriate number of In-Line Heater Update Kits (p/n 0637-240) are being shipped directly to your distributorship. Your distributorship Parts-Account will be charged and then credited upon receipt of a Warranty Claim Request form.

**Warranty:** A labor allowance of 0.5 hr will be paid per affected snowmobile.

Only one vehicle identification number (VIN) can be entered per claim. Do not submit a group claim.

CatTracker Claim: Enter BS200318 in the Complaint section.

Manual Claim: Enter 0318 in the Complaint section.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1102