



Service Advisory

Date: December 27, 2002

Product Line: Snowmobile

Advisory No: SAS314

Subject: Smart Valve/Fuel Pump Update Kit
(p/n 0637-246) - Incorrect Information

Affected Models:

All 2003 Firecat Models Requiring a Fuel Pump Update (see Service Bulletin 2003-1-26)

It has come to our attention that incorrect information was included in Smart Valve/Fuel Pump Update Kit (p/n 0637-246).

On page two of the installation instructions, steps 7 & 8 contain incorrect torque factor information. The correct torque factor for tightening the electrical fitting nut and the fuel pump fitting nut should be 0.7-0.8 kg-m (5-6 ft-lb). Please make the correction and notify all service personnel of this change.

We apologize for the error and thank you for your cooperation in this matter.

Sincerely,

Product Service Department
Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1202