

**Homelite Consumer Products**

**Service Level**  
**MANDATORY**

## **SERVICE BULLETIN**

---

**Product** – Expand-it Tiller Attachment – Models UT15521, UT15521A, UT15521N, UT15550, UT22082, UT22083, UT22084, UT22089

**Identification** – All Expand-it tiller attachments with date code **AC3293XXXX** and higher.

**Condition** – If the gearbox is being replaced, the tines on the left and right side must also be replaced to match the new gearbox “D” shaft design. **Note: if the product is out of warranty, and the consumer approves the cost to replace the gear box, the cost of the service components below will be covered under the warranty.**

**Remedy** – When replacing the gearbox (UT15550A-31) all four tines must be replaced.

### **Service Components Required**

2 ea. Felt Washer ----- UT15550A-36  
2 ea. Clevis and Hinge Pin ----- UT15550A-35  
1 ea. Tine “D” ----- UT15550A-28  
1 ea. Tine “C” ----- UT15550A-27  
1 ea. Tine “B” ----- UT15550A-26  
1 ea. Tine “A” ----- UT15550A-25

### **Service Procedures**

Submit warranty claim using warranty code ----- **EXDTIL0804**  
Warranty claim compensation ----- ½ hour of the current shop labor rate.

For technical assistance contact Homelite technical support at 1-800-2424672