

Homelite

Consumer Products, Inc.
Anderson, SC.

Service Level

MANDATORY

TECHNICAL SERVICE BULLETIN

Product – UT10947, UT10947A

Identification – Homelite 16” 33cc Chain Saw

Condition – When servicing or repairing the chain brake assembly the installation of the service components are required to comply with the improved chassis and brake band design.

Remove the original parts:

UP08721 -----Chassis
UP08097 -----Chain Brake Band Kit
984679001 -----Compression Spring

Service Components Required

1 ea. 985029001 -----Chassis
1 ea. 985030001 -----Brake Band
1 ea. 985021001 -----Chain Brake Cover
3 ea. 82623 -----Screw
1 ea. 985240001 -----Compression Spring

Service Procedures

Replace service components as directed.

Submit warranty claim using warranty code ----- **HCS-SVB1**

Warranty claim compensation ----- 1 hour - based on Hourly Shop Rate

For technical assistance contact Homelite technical support at
1-800-242-4672