

Homelite®

DEALER INFORMATION, TECHNICAL
ADVICE AND PRODUCT INFORMATION
CAN BE OBTAINED AT THIS NUMBER

TECHNICAL SERVICE

1 - 8 0 0 - 4 3 8 - 9 4 7 5

BULLETIN

NO. H98A-016

SUBJECT: BLOWER TUBE SEPARATING

AFFECTS: ALL BLOWERS WITH NON THREADED TUBES

| | | | |
|-----------|-----------|-----------|---------|
| UT08017 | UT08026 | UT08011-B | UT08042 |
| UT08017-A | UT08026-A | UT08011-C | |
| UT08017-B | UT08026-B | UT08011-D | |
| UT08017-C | UT08026-C | UT08011-E | |
| UT08017-D | UT08026-D | UT08011-F | |
| UT08017-E | UT08026-F | UT08011-H | |
| UT08017-F | UT08026-G | UT08011-J | |
| UT08017-G | UT08026-H | | |
| UT08017-H | UR08026-J | | |
| UT08017-J | | | |
| UT08017-K | | | |

The above service kit, Homelite part number **UP02990**, contains ratchet fasteners that can be installed to prevent the blower tubes from separating in normal operation.

Installation is simple and instructions are included with the kit. This kit is for use on blowers with non-threaded tubes only.

Job Code **CV63**
Time **.4**



Bill Borachok
Product Service Manager

DATED: 12/98