



<p>SERVICE BULLETIN</p> <p>INDEX</p>
--

BULLETIN NO.	INFORMATIONAL	DATE
101	Cracked Flywheels	6/95
102	Crankshaft Straighteners	6/95
103	Accessories Installed on Tecumseh Engines	6/95
104	O.E.M. Supplied Gas Tanks	6/95
105	Warranty Repair Not Extending Warranty	6/95
106	Vibration	6/95
107	Rotary Mower Safety Specifications	6/95
108	Gas & Oil Recommendations	10/98
109	Explaining Neglect	6/95
110	High Altitude Carburetor Kits for Fixed Main Carburetors	7/97
111	Storage	10/98
112	Inspection of Brake-Assist Safety Components	
113	Analysis of Field Failure Exhaust Valves	6/95
114	Replacement of 590420A Rewind Starter	6/95
115	New Walbro Fuel Pump	6/95
116	Recoil Identification	6/98
117	Hot Restart Difficulty and/or Hard Starting on Ariens Rotary Mowers	6/95
118	Safety Switches Installed in Starter and/or Ignition Circuit	6/95
119	120 Volt Starter Switch Repair	2/99
120	Incorrect Specification Numbers on MTD Products' Chipper/Vacuum	10/96
121	NO LONGER IN EFFECT AS OF 5 / 1 / 98	
122	Recoil Starter Will Not Engage When Pulled	12/99
123	Accurate Warranty Claim Information	9/98
124	Improved Gear Product Identification	9/98
125/Addendum	Damaged Fuel Line	8/99

2-CYCLE ENGINE BULLETINS


201	Muffler Bolt Torque Retention	6/95
202	Low Power on Feldman Model 30's	6/95
203	Low Power on Strike Master Cobra	6/95
204	Carburetor and Adapter Built Prior to Serial No. 4074	6/95

MOTION DRIVE (PEERLESS®) BULLETINS

301	Bentonite Grease	6/95
302	Peerless® Hydrostatic Drive Units	6/95
303	Assembly Discrepancy - 801-059B SER 5048	6/95
304	Peerless® Transaxles and Transmissions Shifting Problems	6/96
305	NO LONGER IN EFFECT AS OF 7 / 1 / 96	
306	Axle Spline Failure	6/97
307	UNITED STATES ONLY - Peerless® Model VST205 WARRANTY	
	Replacement Program	10/97
308	Hydrostatic Transaxle Shift Force	12/98

SERVICE BULLETIN

INDEX [cont.]



BULLETIN NO. EMISSION INFORMATIONAL BULLETINS DATE

4-CYCLE ENGINE BULLETINS

401	Excessive Valve Clearance caused by Rocker Arm Nuts backing off	6/95
402	Procedure for Addressing High Altitude on OH Engines	6/95
403	VLV50, 55 Fuel Starvation	6/95
404	NO LONGER IN EFFECT	
405	NO LONGER IN EFFECT AS OF 9 / 30 / 97	
406	Smoking Out of Muffler on Initial Start Up	10/98
407	Hot Restarting of Swisher String Trimmer Mowers on Model LEV120-361052B	5/99
408	Hot Restarting of Swisher String Trimmer Mowers on Model LEV115-350127D	5/99
409	220 Volt Electric Starter Safety Rework Procedure - Europe Only	10/99
410	220 Volt Electric Starter Recall - Europe Only	10/99
411	Hard Starting in Cold Weather - Models HM80-100 and TVM195-220	2/00

501	UNITED STATES ONLY - Engine Model Concerned: LEV115, D.O.M. Affected 8091-8166	6/98
502	UNITED STATES ONLY - Engine Models Concerned: H35 & H40; D.O.M. Affected 8079-8201	8/98
503	Rich Running Engines Above 7,000 Feet for Models HM, HMSK, OHSK	1/99
504	Emissions Control System	7/99

PAGE NO. WARRANTY

1	Tecumseh Products Company Limited Warranty for New Engines
2	What is not considered Tecumseh Engine Warranty
3	New Peerless® Gear Power Train Component Warranty
4	What is not considered Faulty Workmanship and/or Material under the Peerless® Drive Train Limited Warranty
5-6-7	Warranty Policy and Procedure for all Tecumseh Registered Servicing Accounts
7	Sears Craftsman engine warranty policy and procedure