



Service Bulletin

Date: July 28, 2000

Model(s): 2001 500 ATV
(Manual Transmission)

Bulletin No: 01-02A

VIN: E11T312492 through E41T312521 (Red)
831T312522 through 871T312636 (Green)

Product Line: ATV

Subject: Side Panel (RH)

Condition: It has been determined that the right-hand side panel on affected models was inadvertently scratched during production.

Solution: Replace the existing right-hand side panel with a new panel to be sent directly to your dealership.

■ **NOTE:** If any customer has taken possession of an affected ATV, please make arrangements with the customer to have the necessary service work completed.

Parts: Update Kit (p/n 0437-012 or 0437-011) will be sent directly to your dealership. **Do not order from Arctic Cat Service Parts Department.** Your dealership Parts Account will be billed for the parts and credited upon receipt of a Warranty Claim Form from your dealership.

Warranty: A labor allowance of 0.4 hr will be paid per affected ATV.

A Warranty Claim Form of up to 10 vehicle identification numbers (VIN) will be accepted.

Write 01-02A in the Failure Code section of the Warranty Claim Form.

