



Service Bulletin

Date: May 5, 2006

Product Line: OHUV

Bulletin No: 2007-6-01

Subject: Brake Rod

Affected Models/VIN:

2002 SBS 1000 Utility Vehicle (All)

Model No: U2002SBM2AUSG

VIN Range: 4UF02UVVC2W000100 - 4UF02UVVC2W000400

Condition:

The original (production) brake rod may fracture which will result in the complete loss of braking. If this condition should occur, serious bodily injury or death may occur.

■ **NOTE:** This is a Mandatory Repair.

Solution:

Install Brake Rod Kit (p/n 0437-050) per instructions included with the kit.

■ **NOTE:** Arctic Cat will contact all registered owners concerning this issue. A copy of the letter is enclosed for your reference.

Parts:

Order an appropriate number of Brake Rod Kits (p/n 0437-050) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty:

A labor allowance of 0.6 hr will be paid per affected vehicle.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.

