



Product Safety Alert

Date: February 12, 2008

Product Line: Snowmobile

Bulletin No: 2008-1-08

Subject: Gas Tank Gauge

Affected Models: 2008 Bearcat W/T (Model No. S2008BCFWTNR, S2008BCFAWNAR, and S2008BCFTWNAR)

What is the reason for this notice?

It has been determined that the gas gauge on the affected 2008 Bearcat W/T does not meet Arctic Cat standards and may cause a possible fuel leak.

What is the problem?

The gas gauge may come in contact with the bottom of the gas tank causing it to possibly separate from the gas tank assembly.

What is the solution?

Install new Gas Gauge (p/n 1670-725).

WARNING

Whenever any maintenance or inspection is performed on the fuel system during which there may be fuel leakage, there should be no welding, smoking, open flames, etc., in the area.

WARNING

Do not sell, operate, or allow anyone to operate an affected vehicle until necessary service work has been completed. Possible fuel leak and fire may result in physical injury or property damage.

Parts: Order an appropriate number of Gas Gauge Kits (p/n 1670-725) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected vehicle.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.