



# Service Bulletin

**Date:** December 12, 2005

**Product Line:** Snowmobile

**Bulletin No:** 2006-1-05

**Subject:** Seat Riser

## Affected Models/VIN Range:

All 2006 Bearcat Wide Track (U.S. & OS), Bearcat Wide Track Turbo (U.S. & OS), and Bearcat Wide Track Turbo Articulating (U.S.) Snowmobiles

**Condition:** At the front of the storage compartment, there exists an opening between the seat riser and the gas tank (both sides). If small items are stored in the storage compartment under the seat, the items could move through the openings and into the engine compartment.

**Solution:** Install Seat Riser Foam Update Kit (p/n 0637-295) per instructions in the kit.

**Parts:** An appropriate number of Seat Riser Foam Kits (p/n 0637-295) will be sent directly to your dealership. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.  
Claim: Enter BS200605 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.

## **ATTENTION**

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to December 12, 2006. All warranty claims directly related to this issue will not be honored after December 12, 2006, without prior approval.

