



Product Safety Alert

Date: February 12, 2008

Product Line: Snowmobile

Bulletin No: 2008-1-07

Subject: Gas Tank Shut-Off Valve

Affected Models: 2008 AC 120 (Model No. S2008ACAAAUSG, S2008ACAAAUSP)

What is the reason for this notice?

It has been determined that the gas tank shut-off valve assembly does not meet Arctic Cat specifications and may cause a possible fuel leak.

What is the problem?

The gas tank shut-off valve may loosen causing the possibility of leaking gas which in turn could present a fire hazard.

What is the solution?

Tighten the gas tank shut-off valve assembly one complete turn. See instructions in this service bulletin.

WARNING

Whenever any maintenance or inspection is performed on the fuel system during which there may be fuel leakage, there should be no welding, smoking, open flames, etc., in the area.

WARNING

Do not sell, operate, or allow anyone to operate an affected vehicle until necessary service work has been completed. Possible fuel leak and fire may result in physical injury or property damage.

Parts: N/A - no parts are needed.

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile.

Instructions:

1. Turn the gas tank shut-off valve to the OFF position.
2. Remove the clamp securing the gasoline hose to the carburetor; then remove the hose from the carburetor fitting.
3. Tighten the gas tank shut-off valve assembly one complete turn.

CAUTION

Do not turn the assembly more than one complete turn or damage may occur.

4. Install and secure the gasoline hose with clamp to the carburetor fitting; then turn the gas tank shut-off valve to the ON position. Inspect for any possible gas leakage.