



Service Advisory

Date: September 18, 2002

Product Line: Snowmobile

Advisory No: SAS303

Subject: Throttle Cable Adjustment

Affected Models/VIN:

2003 Bearcat Wide Track

Model No. S2003BCFWTUSS

Model No. S2003BCFWTOSS (International)

While completing the Snowmobile Setup and Pre-Delivery Instructions on the 2003 Bearcat Wide Track snowmobiles, it is especially important to adjust the throttle cable properly. The throttle cable must be adjusted after the handlebar pad has been installed. If the throttle cable is adjusted before the pad is installed, the installation of the handlebar pad may alter the cable adjustment setting.

Make sure the throttle free-play gap between the Throttle Switch Body and the Throttle Lever is within a range of 0.75-1.5 mm (0.030-0.060 in.) after the handlebar pad has been installed.

■ **NOTE:** It is also important to check/adjust the track alignment after the throttle cable has been adjusted contrary to the order listed in the **SETUP AND PRE-DELIVERY CHECKLIST**.

Thank you for your cooperation in this matter.

Sincerely,

Product Service Department

Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0902