

# Homelite®

DEALER INFORMATION, TECHNICAL  
ADVICE AND PRODUCT INFORMATION  
CAN BE OBTAINED AT THIS NUMBER

**TECHNICAL SERVICE**

**1 - 8 0 0 - 4 3 8 - 9 4 7 5**

## BULLETIN

NO. H98A-015

**SUBJECT: 12" MULTI-PURPOSE SAW WHEEL ARM ASSEMBLY CHANGES**

**AFFECTS: MP38 UT05050, UT05050-A, UT05055  
WHEEL ARM ASSEMBLY PART NUMBER: A02328A**


The **A08337A** wheel arm assembly has replaced the **A02328A** wheel arm assembly for the MP38. The wheel arm has been lengthened to accommodate a 14" wheel used on other multi-purpose saw models.

The following parts are not interchangeable between the two arms.

<b>Wheel Arm Assembly</b>	<b>A08337A</b>	<b>A02328A</b>
Cover, belt	07704	01927
Belt, drive	46068	01926
Arm, wheel	076563A	01917-2

All other parts are interchangeable.

Unique service parts for the A02328A will continued to be supplied.



Peter Knoell  
Product Service Manager

DATED: 12/98