





SERVICE 		4
		B0100017

English 1 (1)

SB, 252 RX, 250 R, Sleeve throttle control shaft, 2001-03

In order to prevent wear to the throttle control shaft caused by the return spring as well as breakage of the return springs there is sleeve available to fit on the throttle control shaft.

The sleeve will be introduced into production on new machines as soon as possible.

New part number	Description	Old part number	Remarks
501 83 29-01	Sleeve		

