





<b>SERVICE</b> 		<b>6</b>
		<b>B0100036</b>

English 1 (1)

## SB, 372 XP, 365 Special, 362 Special, Starter, 2001-05

The starter housing now has additional reinforcing ribs to strengthen it and prevent long wood chips from being sucked into the engine fan. A sleeve has been fitted to the upper front screw. The part number for the starter assembly remains unchanged. New and old parts are fully interchangeable.

New part no.	Description	Excl. part no.	Remark
503 62 82-02	Starter housing assy.	503 62 82-01	
537 08 67-01	Sleeve		

Introduced from serial number:

372	011200001
365	011100601
362	011200001

