





SERVICE 		2
		B0200004

English 1 (1)

SB, 395, Cylinder, 2002-01

The connection has been modified to prevent the manifold from coming loose.

Introduced from serial number: 395 014500151

