





SERVICE 		3
		B020007

English 1 (1)

SB, 325 HS 75, 325 HS 99, Clip for ignition cable, 2002-01

To ensure that the ignition cable is fitted in the correct position a clip has been added to the gear housing. There is no change in the part number for the gear housing assembly.

New part no.	Description	Excl. part no.	Remark
537 17 17-01	Clip for ignition cable		
503 21 27-13	Screw		

*compl 537 06 74-73

