





| | | |
|--|--|-----------------|
| SERVICE  |  | 1 |
| | | B0200041 |

English 1 (1)

SB, 265 RX, Clutch, 2002-05

We have made the clutch shoes 1 mm wider to increase the weight and hence reduce slipping of the clutch.

The clutch shoes retain their original part no., 537 09 77-01. The clutch assembly also has the same part no. as before, 537 09 95-01. The wider shoe has revision letter C. It is 13 mm wide compared with the earlier 12 mm.

NOTE!

Never mix a narrow clutch shoe with a wide clutch shoe when refurbishing a clutch. This would unbalance the clutch, and the clutch shoes would engage at different speeds. This could cause serious engine damage.

Introduced from serial number: 020400116

