





SERVICE 		5
		B0200051

English 1 (1)

SB, 325 HS 75, 325 HS 99, 326 HS 75, Heat shield, 2002-06

There have been some complaints, mainly from countries with warm climates, that the area around the front handle gets too hot. This has been rectified by fitting a modified heat shield that greatly reduces the flow of hot air over the front handle.

The modified heat shield has revision letter M and was introduced into production in week 16 of 2002.

The modified heat shield fits older hedge trimmers.

All the parts in our stock of spare parts have been replaced with revision M.

New part no.	Description	Excl. part no.	Remark
537 06 25-01	Heat shield		Revision M

