





SERVICE 		8
		B0200075

English 1 (1)

## SB, 325 HS 75, 325 HS 99, 326 HS 75, Anti-Vibration Springs, 2002-10

To prevent the springs in the anti-vibration system from becoming overstretched they have been reinforced with movement limiters.

New part no.	Description	Excl. part no.	Remark
537 27 24-01	Rear spring	503 77 08-01	
503 85 38-03	Front spring		Part no. unchanged

