

MODEL } **61**  
 MODÈLE }

#### NEW FUEL TANK

Fuel tank 501 53 42-01 is excluded and replaced by 501 69 90-04, i.e. the same tank as on model 266 SE.

Please note! The roll pin to throttle latch 721 42 12-25 is excluded and replaced by 721 42 12-26.

Roll pin to throttle latch spring is added and has part No. 721 42 09-25.

The change was introduced from serial No.: 5071091

#### NOUVEAU R& ERVOIR À CAR BURANT

Le réservoir à carburant 501 5342-01 a été remplacé par N° 5016990-04, c.-à-d. de même que celui de la 266 SE.

Notez que la goupille fendue du blocage d'accélération N° 7214212-25 a été remplacée par N° 7214212-26.

Une goupille fendue pour le ressort du blocage d'accélération a&d introduite, N° de réf. 7214209-25.

Ces changements ont &d introduits à partir du N° de série: 5071091

