



SERVICE 		4
		X 88.126-26


MODEL **44, (444)**

CARBURETTORS

Carburettor type HDA 24 Ref. No. 501 79 80-01 is excluded and replaced by a "semi-fixed" carburettor type HDA 35 B Ref. No. 503 53 27-01. These carburettors are fully interchangeable.

HDA 35 B: 44,444

H = 1
L = 1 1/2



Introduced from serial No. 44-8020271.

444

NOTE! When changing older carburettors type HDC 51 B Ref. No. 501 45 67-05 to HDA 35 B according to above, the following parts must be mounted also. See below.

Inform your customer that also the function of the starter throttle lock is moved to the choke lever. (See the model 44).

