



SERVICE 		8
		X 88.108-26

MODEL 39 R

THROTTLE HANDLE WITH LOCK AGAINST INVOLUNTARY THROTTLE

In order to increase your safety we have introduced a new handle with lock against involuntary throttle.

This means the following changes,

<u>New Ref. No.</u>	<u>Description</u>	<u>Excluded Ref. No.</u>	<u>Remarks</u>
502 12 18-03	Throttle handle	502 12 18-01	1
502 12 41-01	Handle-half, outside	502 11 68-01	2
502 12 42-01	Handle-half, inside	502 11 69-01	2
502 11 67-01	Throttle trigger lockout	—	1
502 11 70-01	Throttle trigger	—	3
502 11 71-01	Spring	—	3
502 12 64-01	Throttle lock	—	1
503 20 00-05	Screw	—	3
731 23 14-05	Nut	—	3

Remarks:

- 1 = new part
- 2 = remains as a spare part
- 3 = the same part as before

The change is introduced from serial number 7470370.

X) Compl. 502 12 18-03

X) 502 11 71-01

X) 502 12 64-01

