



## MASTER PRO

On models produced during 1990 the assembly of the washer and spring is changed.

On models with side plates there must be a washer between the wheel and the side plate. This washer is missing on certain production batches.

In order to easy remedy this we have a special kit available Ref. No. 516 34 45-00 containing below listed parts.

Ref. No.	Description	Quantity
516 44 07-01	Washer	4
515 11 60-40	Starloc washer	4
516 90 51-00	Circlip	4

