



| | | |
|-------------|--|-------------|
| SERVICE | | 8 |
| | | X 91.125-26 |


MODEL 244 GX, 250 RX, 165 RX

ATTACHMENT OF FLEXIBLE SHAFT TO THROTTLE LEVER

In order to permit simpler and more reliable adjustment of the throttle control the tensioning sleeve has been replaced by screws.

| New Ref. no. | Description | Excluded Ref. no. | Remarks |
|--------------|-------------------------|-------------------|---------|
| 502 14 45-04 | Right handlebar, compl. | 502 14 45-01 | |
| 502 10 68-03 | Tube shaft | 502 10 68-02 | |
| 502 26 45-01 | Locking sleeve | - | * |
| | Tensioning sleeve | 502 10 67-01 | |
| 729 52 86-71 | Screw | . | |

* Remains available as spare part.



NOTE! Make sure that the throttle flap opens fully when the throttle is set to full. Otherwise there is a risk that when you adjust for the recommended maximum speed that the fuel/air mixture will be too lean, resulting in damage to the cylinder or piston. See the instruction book for directions on how to adjust the carburettor.