





SERVICE 		10
		X 91.139-26

MODEL 165 RX

DRIVE SHAFT TUBE

To reduce wear on the drive shaft tube bushings the following improvements have been made:

- Bushings have been made from a new material with better self-lubricating properties.
- When installing the bushings in the drive shaft tube the accuracy of fitting has been increased.

The drive shaft tube ref. no. 502 25 25-01 remains unchanged (fully interchangeable).

To allow easy identification of the improved drive shaft tube, those held as spare parts will be marked with red paint.

Introduced from serial no. 1090001.

