

Models 61, 266, 268, 272, 254, 257, 262, 394

New oil tank ventilation tube

In order to improve the function and to prevent oil leakage, a new design is introduced. The change means that the spiral pin is now mounted inside the plastic tube and then pushed into the crankcase.

New ref. no.	Description	An m
503 66 84-01	Oil tank ventilation tube compl.	262, 257, 254
503 66 84-02	Oil tank ventilation tube compl.	266
503 66 84-03	Oil tank ventilation tube compl.	61, 268, 272
503 66 84-04	Oil tank ventilation tube compl.	394

Oil tank ventilation tube ref. no. 50 18 393-01 and -03 and spiral pin ref. no. 721 42 32-50 remain as spare parts since there is no interchangeability.

NOTE! The spiral pin included in the new design compl. is not the same pin as ref. no. 721 42 32-50.

Introduced from serial number:

- 61 = 3320001
- 268 = 3320001
- 272 = 3320001
- 254 = 3320331
- 257 = 3340001
- 262 = 3310251
- 394 = 3120088

