





SERVICE 		6 X 94.125-26
---	--	------------------

Model **225/232/235**

Recoil spring

Models with serial numbers from 4130001 to serial number 4350001 have been fitted with incorrect recoil springs during production. The incorrect springs can come loose from the starter pulley. This is because the spring only has one free coil in the centre by the eye.

A correct spring has 2,75-3 coils free in the centre. Replace incorrect springs on machines and spare parts.

