





SERVICE 		1
		X 94.142-26


Model 394

In order to receive an improved function, the front left rubber side support is made larger. This prevents the support from changing position in case the saw gets stuck.

NOTE! Only the front left rubber side support is replaced.

New Ref. No.	Description
503 74 30-01	Rubber side support

Introduced from serial number: 4020251



503 74 30-01