





SERVICE 		10
		X 94.153-26

Correction!

Previous bulletin showed wrong ref. no. for tube 240/2435 R.
This bulletin replaces bulletin X 94.153-26

Model 240/245 R/RX

Tube and drive tube

In accordance with requests the tube and drive tube are now available as individual spare parts instead of a complete assembly. The complete tube assembly will no longer be available as a spare part.

New Ref. No.	Description
502 27 42-03	Tube 245 RX
502 11 76-02	Drive tube 245 RX
502 27 42-05	Tube 240/245 R
502 11 76-03	Drive tube 240/245 R

