



Model Royal 48 S

Lawn mower with serial no. 436xxx - 443xxx have got wrongly assembled wire for variator. To remedy this, move the nipple ca 3 mm closer to the bracket. Se Illustration below (A).

