



<b>SERVICE</b> 		<b>5</b>
		X 96.004-26

## Model 232, 235

### Muffler

In those cases where there have been problems with the muffler's mounting bolts becoming loose or shearing off, a third mounting bolt can be fitted. This is possible on machines manufactured in 1995 and later (serial number 501 xxxx and higher), which have cylinders with three mounting holes for the muffler.

One hole with a diameter of 6 mm is drilled in the inner muffler half 502 19 98-01, as shown in the diagram below. The bolt MC 6S 5x16, reference number 725 53 29-55, can be used for mounting.

