



SERVICE 		10
		X 96.013-26

Model 235R

Correction

Unfortunately an incorrect reference number in service bulletin 10 X 95.011-26 was given. This service bulletin replaces earlier editions.

Bevel gear

All components are now available as spare parts.

New Ref. No.	Description	Excl. Ref. No.	Remark
531 00 20-01	Gear housing	-	
503 84 35-01	Gear-wheel spare part kit	-	
531 00 20-02	Cover plate	-	
735 31 14-00	Circlip SGH 12	-	
735 31 28-10	Circlip SGH 28	-	
735 31 33-10	Circlip SGH 35	-	
738 21 01-00	Ball bearing 28x12x8	-	
738 22 02-19	Ball bearing 35x15x11	-	

Other components are still available as before

502 18 50-01	Gear assy.	-
502 04 55-01	Nut	-
502 03 10-03	Support flange assy.	-
502 19 46-01	Driver	-
503 20 02-20	Bolt M5x20	-
503 20 02-25	Bolt M5x25	-
502 19 36-01	Sealing ring	-

