



SERVICE 		1
		X 96.008-26

Model 250R/RX

Clutch

The Teflon bushings in the clutch have been changed to bronze bushings to obtain a clutch that can withstand high temperatures. Also refer to the previous service bulletin 95.007 tab 1. The clutch complete changes number to 502 27 80-02.

New Ref. No.	Description	Excl. Ref. No.	Remark
502 27 80-02	Clutch complete	502 27 80-01	
502 27 78-01	Bronze bushing	502 28 38-01	

Other reference numbers remain as before.

