





SERVICE 		5
		97-08-18

Model 225 E/H/L/LD/R/RD/RJ
232 L/R
235 P/R
240 RBD

Muffler

In the Operator’s manuals for E-tech products, it is informed that ” *the muffler should be changed once a year for full performance*”.

This is not correct. The muffler is designed to last as long as the machine itself.

The machines are approved by the EPA regulations, which also includes an ageing test of the catalytic converter.

Note that the maintenance regarding the spark arrest screen is not concerned in this Service Message, and that a defective muffler always shall be replaced.

If the spark arrest screen often becomes blocked, there is a possibility that the catalytic converter doesn’t work properly. In this case the nearest Husqvarna dealer is to be contacted.

New ref. no.	Description	Excl. ref. no.	Remarks
101 89 15-95	240 RBD	101 88 96-95	Pages 25 and 29
101 89 16-95	225 H	101 89 00-95	Pages 16 and 18
101 89 17-95	232/235 R	101 88 93-95	Pages 23 and 25
101 89 18-95	235 P	101 88 67-95	Pages 17 and 19
101 89 19-95	225 E	101 88 92-95	Pages 18 and 20
101 89 20-95	225 R/RD/RJ	101 88 97-95	Pages 26 and 28
101 89 21-95	225 L/LD, 232 L/Green City Box	101 88 94-95	Pages 23 and 26