





SERVICE 		5
		97-08-18

## Model 235 P

### Muffler

In the Operator's manuals for 235 P E-tech, it is informed that " *the muffler should be changed once a year for full performance*".

This is not correct. The muffler is designed to last as long as the machine itself.

Note that the maintenance regarding the spark arrest screen is not concerned in this Service Message, and that a defective muffler always shall be replaced.

If the spark arrest screen often becomes blocked, there is a possibility that the catalytic converter doesn't work properly. In this case the nearest Husqvarna dealer is to be contacted.

New ref. no.	Description	Excl. ref. no.	Remarks
101 89 18-26	235 P	101 88 67-26	Page 17