


MODEL: Chain Saws

SUBJECT: Fuel Line Splits

When using some reformulated fuels it has been reported that fuel lines split and the filter comes off, then the fuel line will not stay submerged in the fuel mix in the tank. This can produce erratic running and in some cases lean running conditions. There have also been isolated reports experienced at the carburetor fitting.

Should you encounter this you can use part #503 18 49-01 which can be installed over the line to improve durability. Refer to pictures below.



www.mymowerparts.com