






INSPECTION OF BRAKE-ASSIST SAFETY COMPONENTS ON TECUMSEH ENGINES MANUFACTURED IN COMPLIANCE WITH CPSC REGULATION PART 1205 and CANADIAN VOLUNTARY COMPLIANCE STANDARD

As a regular Customer Service, the brake-assist safety components should be inspected whenever a compliance walk-behind lawn mower is brought to you for service. If any of these safety-related parts are worn or operating improperly at any time during the life of the engine, such part(s) should be repaired or replaced under warranty.

<p>OLD</p> <p>Individual components can be replaced.</p> <p>TOP VIEW</p> <p>GROUNDING CLIP POSITION</p> <p>LINK</p> <p>SPRING</p> <p>"E" CLIP</p> <p>BRAKE PAD</p> 	<p>SIDE VIEW</p> <p>TYPICAL BRAKE BRACKET ASSEMBLY</p> 
<p>NEW</p> <p>Complete brake bracket assembly is replaced if worn or damaged.</p> <p>TOP VIEW</p> 	<p>SIDE VIEW</p> <p>TYPICAL BRAKE BRACKET ASSEMBLY</p> 