



Service Kit

753-05579

Date: 9/18/2007

Subject: Service Replacement for the Tiller Wheel Axle Shaft 711-04091

Models Affected: N/A

Read through and understand these instructions completely before proceeding with repair.

PURPOSE: This service kit is the service replacement for the wheel axle shaft, 711-04091, which is no longer available. New wheel assemblies are included due to the design change in the wheel shaft diameter and use of a common wheel rim design.

NOTE: These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.




FIGURE 1

Service Kit Contents

(See Figure 1)

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	634-04232	2	WHEEL ASSEMBLY: COMPLETE: 13" x 5" x 6"
2	710-0606	2	SCREW: 1/4"-20 x 1.50": GR5: STD
3	712-04064	2	NUT: FLANGE LOCK: 1/4"-20: GRF: NYLON
4	711-04482	1	SHAFT: WHEEL
5	GW-9373	1	KEY: HI PROFILE
6	*	1	THIS INSTRUCTION SHEET

* - Not Available Separately