

WHITE OUTDOOR BULLETIN

CODE: W-099

DATE: DECEMBER 10,1996

Models: Single-Stage Snow Throwers SB-50 (317-262-190), SB-55 (317E262-190)

Date: December 4, 1996

Subject: Uneven Shave Plate

PROBLEM:

When placed on a smooth and level surface, such as concrete or blacktop, the shave plate (P/N731-1728) will not set flush on some of the above model snow throwers. When operating, with the handle raised, the shave plate will set flush. Engineering reports that this will not affect either the performance or design life of the unit. However, if the uneven shave plate affects the sale of the unit, refer to the solution below.

SOLUTION:

1. Place the unit on a smooth and level surface.
2. Remove the engine cover/cowling as shown on back of this bulletin.
3. Remove bolt (P/N 710-1088) 5/16 X 1 inch on the left side of the outer frame as shown in figure 1 on the back of this bulletin. This will cause the frame to pivot and allow the shave plate to set flush. Light pressure may be needed on the handle bar.
4. Using the outer frame hole as a template, file inner frame assembly hole to match the outer frame hole.
5. Reassemble.

Warranty allowance: Submit a warranty claim for .5 hour.