



# Service Kit 753-04874

Date: August 5, 2004

Subject: 734-0968 Replacement Wheel

Models Affected: N/A

**PURPOSE:** Use this kit when replacing Wheel and Rim Assembly, 734-0968 (9" diameter x 1.75" wide with a 5/8" bore plastic hub), which is no longer available. The replacement Wheel and Rim Assembly, 734-2010A, is a 9" diameter x 2.12" wide with a 1/2" sleeved bore hub. Hardware is supplied to adapt the new wheel.

**NOTE:** These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

**NOTE:** Save this Instruction Sheet. Refer to it when ordering replacement parts.

## Service Kit Contents (See Figure 1)

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	734-2010A	1	WHEEL: COMPLETE: 9" X 2.12"
2	710-0182	1	HEX BOLT: 1/2"-13 X 3.0" LG GR5
3	712-3048	1	NUT: JAM: 1/2"-13
4	712-3083	1	NUT: HEX LOCK: 1/2"-13 (NYLON)
5	736-0160	3	FLAT WASHER: .53" x .93" x .050"
6	*	1	THIS INSTRUCTION SHEET

\* - Not Available Separately




FIGURE 1

### Installation Instructions:

