

Service Advisory

W-159

TRACTOR

Models Affected: OEM-190-032 and 190-032-101

Serial Number Range Affected:

N/A

Date: October 2, 2008


Subject: 42" 2-Stage Snow Thrower Attachment Heat Shield.

ACTION REQUIRED: This advisory is **INFORMATIONAL ONLY**

PURPOSE: This informational advisory addresses the 42" 2-stage snow thrower attachment's heat shield usage and rider model configuration.

DISCUSSION:

For riders that have the raised side discharge muffler, see Figure 1, the snow thrower's heat shield, see Figure 2, is not required. The heat shield should be removed before attaching the snow thrower attachment to the rider.



Remove Heat Shield from Snow Thrower

Snow thrower's heat shield interference with

FIGURE 1

FIGURE 2

For riders that have the lower forward discharge muffler, see Figure 3, the snow thrower's heat shield must remain on the snow thrower attachment to protect the gear box.




FIGURE 3

This Advisory is being released for informational purposes only

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.