



Service Bulletin

Date: Sept 11, 2000

Model(s): 2000 Z 120

Bulletin No: 01-02

VIN: Not Applicable

Product Line: Snowmobile

Subject: Rear Suspension Spring

Condition: It has been determined that the rear suspension spring on the affected model may fail under certain conditions.

Solution: If rear suspension spring failure occurs, install Spring Replacement Kit (p/n 0704-562).

Parts: Order the appropriate number of Spring Replacement Kit (p/n 0704-562) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of Warranty Claim Form(s) from your dealership.

Warranty: A labor allowance of 0.5 hr will be paid per affected snowmobile.
A Warranty Claim Form of up to 10 vehicle identification numbers (VIN) will be accepted.
Enter 01-02 in the Failure Code section of the Warranty Claim Form.

