



Service Bulletin

Date: September 6, 2002

Product Line: Snowmobile

Bulletin No: 2003-1-04

Subject: Battery Fluid Lines

Affected Models / VIN:

■ **NOTE:** Each affected model below will have a vehicle identification number (VIN) within a VIN range beginning with the first set of numbers and ending with the last set of numbers. It is necessary to refer to only the last six digits of the VIN to identify an affected snowmobile.

Affected Models:

Model: 2003 Z 370 es (Black)

Model No. S2003ZAAESUSB (es)

VIN Range: 4UF03SNW63T148746 through 4UF03SNW13T149495

Model: 2003 Z 440 esr (Black)

Model No. S2003ZABERUSB

VIN Range: 4UF03SNW33T149996 through 4UF03SNW23T150090

Model: 2003 ZL 550 esr (Black)

Model No. S2003ZLCERUSB

VIN Range: 4UF03SNWX3T150936 through 4UF03SNW73T151235

Model: 2003 ZL 550 esr (Silver)

Model No. 2003ZLCERUSM

VIN Range: 4UF03SNW93T151236 through 4UF03SNW93T151835

Model: 2003 Pantera 550

Model No. S2003PTCCAUSC

VIN Range: 4UF03SNW03T151836 through 4UF03SNW63T152716

Model: 2003 Pantera 550 OS

Model No. S2003PTCCAOSC

VIN Range: 4UF03SNW83T152717 through 4UF03SNW43T152861

Condition: It has been determined that the batteries installed in the affected models may not contain upper and lower fluid lines. Since it is imperative that the correct level of battery fluid is maintained, upper and lower fluid lines must be added to the affected batteries.

Solution: Inspect the battery on the affected models to determine if the battery contains upper and lower fluid lines. If the battery does not contain the appropriate lines, install Battery Decal (p/n 0411-600) for Z 370 es and Z 440 esr models. Install Battery Decal (p/n 5611-203) for the ZL 550 esr, and Pantera 550 models indicated on this bulletin.

■ **NOTE:** Affix the appropriate decal to the battery with the top of the decal positioned immediately below the bottom edge of the battery cover. Make sure the battery area where the decal is affixed is thoroughly cleaned and dried prior to affixing the decal.

Please contact owners of an affected snowmobile concerning this issue and make arrangements to have the necessary service work completed.

Parts: Order an appropriate number of Battery Decal (p/n 0411-600) and/or Battery Decal (p/n 5611-203) through normal parts-ordering channels. Your dealership parts-account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ **NOTE: The battery decals will be available on approximately October 1. Any orders placed prior to this date will be shipped as soon as the decals are available.**

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile.

Only one vehicle identification number (VIN) per claim can be entered.

CatTracker Claim - Enter BS200304 in the Complaint section

Manual Claim - Enter 0304 in the Complaint section



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0902