



Product Safety Recall Bulletin

Date: May 16, 2006

Product Line: Utility Vehicle

Bulletin No: 2007-6-02

Subject: Rear Brake Caliper

Affected Models/VIN:

All 2006 Prowler XT vehicles within the VIN range of 4UF06MPVO6T300001 - 4UF06MPV16T302369

■ **NOTE:** For identification purposes, it is necessary to refer to only the last six digits of the VIN.

What is the reason for this notice?

In cooperation with the Canadian Department of Transport, Arctic Cat is voluntarily replacing the rear brake caliper on (2,369) 2006 Prowler XT models.

Stop Sale Immediately of 2006 Prowler XT models which contain a vehicle identification number within the VIN range indicated above.

What is the problem?

On some vehicles within the indicated VIN range above, the rear brake caliper may leak fluid through the rear mechanical shaft boot. If this condition exists over a period of time, a loss of rear braking ability will occur.

WARNING

Do not operate or permit anyone to operate any 2006 Prowler XT within the VIN range indicated above until the rear brake caliper has been replaced.

■ **NOTE:** This condition applies only to the rear brake system. The front brake system will operate normally.

What should you do?

1. Please contact all customers who have taken possession of an affected 2006 Prowler XT.

■ **NOTE:** Arctic Cat will contact all registered owners concerning this Product Safety Recall Bulletin (letter is enclosed).

2. Install Rear Brake Caliper Update Kit (p/n 0437-051) per instructions enclosed with the kit.

■ **NOTE:** Please make every attempt to install the update kit on vehicles that have already been sold and released to customers before installing the kit on unsold vehicles that are still at your dealership.

Parts: Order an appropriate number of Rear Brake Caliper Update Kits (p/n 0437-051) through normal parts ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form and the return of the existing rear brake caliper.

■ **NOTE:** The rear brake caliper must be held for 90 days. Within the 90-day period, Arctic Cat will send you a parts return notice. Do not send the caliper back when submitting your warranty claim.

Warranty: A labor allowance of 1.0 hr will be paid per affected vehicle.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.